Field Service Bulletin No. 18

Order No.: DD+DIS224.01E

1 piece UQHFA MA1

ADC Solo
Type 5155/100

Path Speed CR SP 1001
Type 5155/200

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X				X

Please file this document in section 13 of your technical documentation

New designed Energy Chain of Cassette Unit introduced

1 Symptom

In cases of often occurring problems with the cassette unit related to the I/O-Bus, it is recommended to replace the energy chain by the new one.

2 Defect

The energy chain is defective. Contact problems occur while the cassette is moved to the alignment.

3 Solution

Replace the energy chain of the cassette unit by the new one:

3.1 Order Number

Energy chain module for cassette unit: **CM+9.5155.9200.0**

printed in Germany 09 / 2001

AGFA

3.2 Scope of Delivery

1 x energy chain for cassette unit
5 x screws
1 x cable
1 x pipe clamp
6 x cable ties
1 x floppy
1 x documentation

3.3 Position of the Unit

View from left side with opened housing